			3.30 Patch 2 ITS Weekly FW start here		
N/A	Internal	N/A	QuickSec rekeying switch enhancement	N/A	This enhancement is for the device without IPsec rekeying function.
N/A	Internal	N/A	ZyLog Enhancement for QuickSec engine	N/A	ZyLog Enhancement for QuickSec engine for debug usage.
N/A	Internal	N/A	Memory leak in DNS Inbound Load Balancing module.	N/A	Memory leak in DNS Inbound Load Balancing module.
Medium	130401361	Coventry	Reboot	USG300	USG300 has reboot problem with a cycle.
Low	130701485	DE	USG 50 - SNMP Status	USG50	USG 50 SNMP status is wrong. SPR: 1307221709
High	130801770	CH	USG1000: HA Backup FW 99% CPU	USG1000	USG1000: HA Backup FW 99% CPU SPR: 1308303581
Low	130704361	DE	ADP log problem	USG300	The source address of ADP log will be the IP address which is after NAT.
High	130802428	CH	USG1000: HA synch. does not work	USG1000	We add an enhancement that Device-HA sync will include IDP customize signature.
Low	130802620	Taiwan	USG300 Online Helps has wrong description in Content filter.	USG300	The description for "Forbidden Web Sites" is incorrect in the online help. It should be *bad-site.com, not bad-site.com.
Medium	130803743	DE	USG-20W / NAT can´t work to Server with BR1 WIFI	USG20W	USG will not save the MAC address. SPR: 130903152
Medium	130103364	DE	[AIM SOFTWARE] USG-1000 / SNMP with High Ping/CPU and Througout Issue	USG1000	SNMP will occupy CPU resource.
Low	130905885	CZ	USG 300 and alerts	USG300	Customer concern that there is not needed in HA "alert" that "Version for Certificates is the same, skip update", this can be ok like log.
Medium	131001353	DE	USG 3.30 / Dynu DDNS cannot work as with .net	USG50	Dynu DDNS cannot work as with .net

Medium	131004038	DE	USG FW 3.30 (Patch 1) ESP fragmentation	USG100	When packet size larger than MTU value, the Don't fragment bit of ESP packet is still setup on and then USG gets a "destination unreachable (Fragmentation needed)" from WAN's gateway.
N/A	Internal	N/A	QuickSec Performance Tuning	N/A	QuickSec Performance Tuning
N/A	Internal	N/A	[PPTP] Set connection ID with "dot", the PPTP interface will not be create.	N/A	[PPTP] Set connection ID with "dot", the PPTP interface will not be create. SPR: 31126467
N/A	Internal	N/A	3.30 MyZyxel 2.0 will cause some issue on AV/CF service.	N/A	1. ZAV expired. KAV is licensed. DUT is set KAV. User fails to update AV signature. 2. BlueCoat CF license expired. Commtouch is licensed. Change CF from BlueCoat to Commtouch fail.
Medium	130900205	Italy	https management on port 10444	USG20	The customer change the HTTPs port as 10444, then the GUI can't open any more. SPR: 130904308
Medium	131003539	SK	Content Filter - Incorrectly displayed Deny message in Windows 7	USG300	If there is configured Content filtering HTTP Web Category Filtering and users issues denied Web Page, in Internet Explorer is not correctly displayed Denied Access Message which is configured on USG, and only displays "Page cannot be displayed" which not the Denied Access Message.
Low	131102290	Sweden	USG 2000 - Memory/CPU usage	USG2000	Customer's USG2000 is very often at very high memory usage, at the moment 96%. There is no command to show the details of the memory usage. We add a new CLI command "debug system drop-caches" to drop the inactive memory.

Low	131100487	NL	IOP issue between USG 20/100/200 and ZyWALL 110 Ethernet WAN port and Genexis FiberXport OCG-1012m_v1	USG20/20W/50	If we connect USG WAN port to Genexis FiberXport OCG-1012m_v1, USG can't get WAN IP. If we setup a switch between USG WAN port and Genexis FiberXport OCG-1012m_v1, then USG can get WAN IP.
Low	131104862	UK	USG20 - lots of request to CF DNS server	USG20	There are lots of requests per second to those DNS server. cf.zyxel.com iprep1.zyxel.ctmail.com iprep5.zyxel.ctmail.com iprep2,3,4 etc SPR: 131203217
Medium	131103596	CZ	USG 100 and BWM doesn´t work ok	USG100	When set up BWM: Incoming Interface: lan1; Outgoing Interface: wan1; Inbound/Outbound: 512kbps, But only download Bandwidth can be controlled as speedtest result (0.55Mbps/13.42Mbps). SPR: 131204321
Low	131005943	CZ	USG 100 and daily logs	USG100	Email Daily Report logs graphs are empty. SPR: 131111615
Medium	131102399	Coventry	Problems with port statistics	USG20	1. When PC1 is connected to USG port2 we have normal port statistics (graphic and grid). 2. When we connect PC2 to the port3 the statistics for port2 still appears but the graphic for port3 doesn't work. Tx B/s and Rx B/s still= 0 for port3 (as attached "pic-1") even if we are sure the traffic from PC2 currently exists. After reboot of USG the statistics shows for both ports in normal way. SPR: 131202059

Low	131006197	DE	Copyright information of ZW 310 shows 1995 -2007...	ZW310	When DUT sends Daily report, ending of daily report information, there is a sentence makes customer feel bad.
Low	131004935	CH	Request for SOP	USG1000	The customer used Win8.1 to establish the SSL full tunnel mode. And enabled "Force all client traffic to enter SSL VPN tunnel" function. But seems not work.
Medium	131100618	US	Change Device-HA setting cause WEB GUI timeout after enabling this function	USG300	We have to wait the WEB GUI back if adding monitor interface after enabling Device-HA.
High	131005908	CH	USG100: FW 3.30 cannot achiv same performance as FW 3.00	USG100	The customer concern the 3.30 firmware will cause bed performance. Also customer has upgraded the firmware to 3.30 patch 2, but if enable BWM through put still not good. SPR: 1311201126
Low	130803915	DE	traffic will be drpped randomly	USG200	The traffic of server 192.168.10.5 will be dropped by the firewall rule randomly. The customer needs to reboot the USG to recover it.
Medium	131005078	DE	USG200 Problems with WAN1 when setup connectivity-check	USG200	WAN1 is DHCP client role and configured connectivity-check for its gateway. From syslog, it shows WAN1 is set to DEAD frequently without reason.
Medium	131002462	CH	USG-100 CPU high when deleting several phase 1 or phase 2 vpn rules.	USG100	The customer's concern is if delete few IPSec rules (phase 1 or phase 2), the device will not response any more. SPR: 1312171094
Medium	131100133	CH	USG-50 Dyna premium not working	USG50	In Dynu Premium setting of DDNS, the warning note should hind in user name check box. SPR: 1312171095
Medium	131005922	France	[USG 100] AD Alternative Login Attribute	USG100	AD Alternative Login Name Attribute can't work on firmware 3.30, it works on firmware 3.00. SPR: 131105256

Critical	130905233	DE	USG-2000 / WK27 and WK33 crash by boot progress or first tunnel established	USG2000	Device HA is disabled on both devices before upgrading to debug FW WK37. After FW upgrading, the ZySH daemon dead. After removing the configuration of device HA then uploading the revised configuration to the device, it works and is back to normal. SPR: 131104173
Medium	131000402	Philippines	USG 300 some config are missing	USG300	Some configurations such as IP MAC binding and content filtering policy can't be completely uploaded to device after the attached configuration file is applied. SPR: 131000402
			WK49-r47031 (2013/12/05) End		
			3.30 Patch 4 ITS Weekly FW start here		
N/A	Internal	N/A	[Zysh]Use Ixload do Stress test CF daemon is dead.	N/A	Use Ixload do Stress , CF daemon is dead. SPR: 131126459
Low	131104862	UK	USG20 - lots of request to CF DNS server	USG20	There are lots of requests per second to those DNS server. cf.zyxel.com iprep1.zyxel.ctmail.com iprep5.zyxel.ctmail.com iprep2,3,4 etc
Medium	131203698	Tanzania	New model of Huawei E303 dongle not compatible	USG100	Customer has issues with a new version of Huawei E303 dongle with firmware version: 22.158.13.00.73.
Low	131202199	PL	GPRS/EDGE commands for 3G modem	USG100	Since customer need using GPRS/EDGE because in his office GPRS/EDGE is much more stable then WCDMA in Poland, But when customer chooses option "GPRS/EDGE (GSM) only", then they using Monitor on device, still stay in WCDMA. SPR: 1401241253

Medium	140101349	CN	SSL VPN login will show internal error	USG200	SSL VPN Full tunnel mode doesn't work.
Medium	130902058	Coventry	USG100 - USB Flash	USG100	Device has hang issue, because IPSec VPN daemon loop.
Medium	140103025	CZ	USG 100 cannot change default password after first set up	USG100	USG in defaults, customer log in and change password to different one based WEB GUI request, this new password work fine but USG save it only in running configuration and not to startup config, and after switch off/on or reboot USG it will back to original password. SPR: 1401281429
Critical	140102361	CH	Activation of Commtouch CF not possible	USG50	The device activated CF Commtouch service and Bluecoat without service. Then uploaded the configuration with Bluecoat configuration. After applied the configuration and reboot the device, the device shows error message in console.
			WK03-r48689 (2014/01/20) End		
N/A	Internal	N/A	ZyLog Enhancement for QuickSec	N/A	ZyLog Enhancement for QuickSec
N/A	Internal	N/A	Turn off dhcp arp_check in USG20W default configuration.	USG20W	Turn off dhcp arp_check in USG20W default configuration.
N/A	Internal	N/A	Support wlan config file which support bridge interface with lan1/lan2/dmz/wlan-1-1	N/A	Support wlan config file which support bridge interface with lan1/lan2/dmz/wlan-1-1
N/A	Internal	N/A	[SSL VPN] RDP is not success for each test.	N/A	[SSL VPN] RDP is not success for each test. SPR: 131220299
Medium	140104045	DE	USG20 / DDNS (noip) feature enhanced.	USG20	NO-IP DDNS provider has enhanced a feature called sub-account to avoid mistake updating. USG cannot support the sub-account format with ":" in configuration field.

Critical	140201672	DE	USG-300 / crash totally after create 23 VLAN	USG300	USG-300 with 23 configured VLANS (just create). When modify and click OK the CPU go up to 99% for a few minutes 3-6 minutes. Fixed two issue in WK03: 1. Cannot add a new VLAN interface through GUI interface. 2. Collect diagnostic info will cause device crash.
Medium	140103024	DE	USG-20 / alert ,system ,App Watch Dog	USG20	When wan1_ppp disconnected and re-connect, the ZyWALL show "alter System App Atachdog reach 97%" issue.
			WK05-r49065 (2014/02/14) End		
N/A	Internal	N/A	Stress on USG300, device crash.	N/A	Stress on USG300, device crash.
N/A	Internal	N/A	Device always shows CPU high but CPU is not high actually	N/A	Device always shows CPU high but CPU is not high actually SRP: 140227779
N/A	Internal	N/A	Extended arp entry size to 65536	N/A	Only on USG1000 and USG2000.
High	140103540	CZ	ZyWALL 110, AD, L2TP VPN doesn´t pass	ZW110	Customer using Windows 2008 and older can build L2TP from AD server work fine, But from 2008R2 and next (AD server 2012 "virtual server") doesn´t work in same condition.
Medium	140200748	India	SSL VPN not working	USG100	The customer usually gets the message "Cannot create Tap routing interface. Please logout and retry again." after SSL VPN is logged in.
Low	140201667	UK	USG 1000 / PCI Compliance /3097	USG1000	PCI Compliance failed.
Low	140103672	Sweden	SSH key support USG 1000?	All	SSH daemon with public key authentication disabled

High	140203461	.ec	USG1000 / CF enable and download file from keepvid issue.	USG1000	CF service is enabled, the download speed decreases to 30KB ~ 0KB. CF service is disabled, the download speed back to normal (around 2000 KB)
			WK07-r49566(2014/03/03)End		
N/A	N/A	N/A	pro daemon dead.	N/A	Use domain name to access revProxy url.
N/A	N/A	N/A	Add SMTP port change and SMTP TLS support for log settings and email daily report	N/A	Add SMTP port change and SMTP TLS support for log settings and email daily report
Medium	140203512	Coventry	USG50 - Antivirus	USG50	Customer daily reports on mail message can't sync with real license status.
Low	140203590	Sweden	CLI: 49 Error Code: -53000	USG100-Plus	The customer claims that he gets the error message on USG100-PLUS after a while (around 10 minutes) when he is logged on to the dashboard CLI: 49 Error Code: -53000
High	140204106	DE	USG100plus - Cannot update AV Signature - FW 3.30 Patch 4 / ITS WK05	USG100-Plus	Customer has a new USG100plus. He activated device on MyZyXEL.com 2.0 and AV / IDP services. But, he cannot update AV signature successfully. The AV signature version was Anti-Virus Engine Type: ZyXEL 2.0 Current Version: 0000 Signature Number: 0000 Released Date: n/a SPR: 140314501
High	140203489	TW	Static IP address on ZLD 3.30 Device-HA legacy mode will be 0.0.0.0	USG2000	Static IP address on ZLD 3.30 Device-HA legacy mode will be 0.0.0.0, and the LAN traffic cannot go out. SRP: 140310265

			WK09-r49920(2014/03/17)End		
N/A	Internal	N/A	Force to change MyZyXEL to version 2.0	N/A	Force to change MyZyXEL to version 2.0
N/A	Internal	N/A	If my address set 0.0.0.0 and Peer Gateway set domain name in IPSec VPN Phase1 , IPSec VPN cannot be established.	N/A	If my address set 0.0.0.0 and Peer Gateway set domain name in IPSec VPN Phase1 , IPSec VPN cannot be established. SPR: 140314584
Low	140300657	Sweden	VPN setup wizard issue	USG300	When using wizard to create a new VPN policy, there is a risk of overwriting and old address object if it has the same policy name as the new policy.
Medium	140201212	DE	USG-300 / IPv6 issues crash ZySH dead	USG300	Incorrect Firewall filtering of IPv6-Traffic if destination Object is IPv6-Subnet having prefix other than /64.
Low	131102290	Sweden	USG 2000 - Memory/CPU usage (#131203383)	USG2000	Customer's USG2000 is very often at very high memory usage, at the moment 96%. We add a CLI command to manually free memory." debug system free-more-memory"
Low	131204955	DE	NAT rule is not working after a period time.	USG20W	When device is running a period time, the 1:1 NAT rule is not working as well.
Medium	140302321	Coventry	USG100 - Configure with BWM becomes default	USG100	Customer configuration file at Policy BWM #127 becomes default.
Critical	140302055	CH	Zywall USG Series	wrong registration page after firmware update from 3.00 AQQ.4 to 3.30 AQQ.4	USG Series	If turn on USG and without internet connection. After finished booting process, the device registration page will keep on myzyxel.com 1.0. If connect with internet, the device will register to myzyxel.com 1.0 but not 2.0.
			WK11-r50390(2014/03/31)End		
High	140302259	DE	USG-300 / again IPv6 issue in firewall and address module	USG300	When firewall rule activate, the firewall function blocks traffic even the source IP is not defined in the firewall rule. SPR: 140414636

Critical	131107014	DE	USG-2000 / urgent VPN issue Skidata, ZySH dead, no vpn´s can build	USG2000	After upgrade from 3.00 WK37 to 3.30 WK43 the ZySH daemon crash the USG boot and VPN´s can´t established.
High	140301445	Fr	[USG] Anti-Spam issue	USG100	When enabling Anti-Spam function. If receiving the mail with attachment(over 3 MB), then the client can't receive success.
Medium	140300757	DE	USG-Series - German WebGUI login screen shows -Need Translate- point-4	USG Series	In German language platform, It is wrong of 4th note in main login page.
			WK13-r50709(2014/04/14)End		
N/A	Internal	N/A	SSLVPN SecuExtender upgrade from 3.0.19.0 to 3.0.20.0	N/A	SSLVPN SecuExtender upgrade from 3.0.19.0 to 3.0.20.0
N/A	Internal	N/A	IPSec tunnel, one side press disconnect button successful but the other side still show connected icon.	N/A	IPSec tunnel, one side press disconnect button successful but the other side still show connected icon. SPR: 140423212
Low	140400393	UK	USG 100 / Authe Policy Behavior	USG100	Auth policy will revert back to force.
Low	131201085	AU	USG VPN IPSec failure	USG300	SPI:0x0 SEQ:0x0 No rule found, Dropping packet.
Low	140201613	Sweden	USG 50 - L2TP issue	USG50	The L2TP tunnel goes up without any issues and traffic can be sent via the VPN tunnel. After approximately 1 minute to 60 minutes the L2TP VPN tunnel suddenly goes down. SPR: 140401005
Medium	131205712	Denmark	USG 2000 - L2TP issue	USG2000	The L2TP tunnel goes up without any issues and traffic can be sent via the VPN tunnel. After a while (less than an hour) the L2TP VPN tunnel suddenly goes down, and re-connection takes a long time. SPR: 140401005

Low	140300566	Sweden	RDP USG not working with flash	USG50	This is an old ticket(#130200113) reported in 2013 February. When connecting trough RDP by SSL VPN and then surfing the Internet, the user lose connection to RDP machine.
Critical	140400954	Tr	content filter error	USG300	When enabling the Content Filter function, it will pop out the error message, and can't access to internet any more.
Medium	140401175	India	Unknown Error comes after enable content filter in USG-200	USG200	After enabling content filter, an error message pops up.
High	140401076	UK	USG 200 High CPU Usage	USG200	CPU is high on DHCPD process.
Medium	140302644	DE	SMTP TLS / Daily-Report does not work since WK09	USG200	Email Daily Report seems like not working as well even click Send Report Now button, there is no any SMTP packet send out from USG.
Medium	140401282	DE	USG-100 / SSL VPN with IE 11 fails RDP (White page)	USG100	Win 8 + IE11 connects to reverse(proxy) SSL VPN and click RDP application, the page of RDP application is white.
			WK15-r51212(2014/04/28)End		
N/A	Internal	N/A	[CF] Unknown engine type problem cause can't search local cache issue.	N/A	[CF] Unknown engine type problem cause can't search local cache issue. SPR: 140508537
Medium	140400564	Coventry	USG-300. SSL VPN Applications Feature Request	USG300	Customer need SSL Server address can be sorted by alphabetical order from A to Z.
Medium	140500164	DE	USG-200 / SSL VPN Secu Extender can´t login after firmware upgrading	USG100	SecuExtender account cannot be login after device's firmware upgrading from 3.00 patch2 to 3.30 patch4. (Even 3.30 p4 wk13) The SSL VPN login page becomes user aware page.
Low	140500365	UK	USG 50 SNMP Issue	USG50	No SNMP information.

			WK17-r51759(2014/05/12)End		
N/A	Internal	N/A	Make priority of IDP/AV hook in forward chain to become lower than zypktorder such that IDP/AV can receive in order packets to process.	N/A	Make priority of IDP/AV hook in forward chain to become lower than zypktorder such that IDP/AV can receive in order packets to process.
N/A	Internal	N/A	change the default action of DHCP ARP check	N/A	change the default action of DHCP ARP check Was: default action is enabled. Is: default action is disabled.
N/A	Internal	N/A	IPsec rekey failed in L2TP when IKE SA is unavailable.	N/A	IPsec rekey failed in L2TP when IKE SA is unavailable.
N/A	Internal	N/A	L2TP rekey failed while doing stress	N/A	L2TP rekey failed while doing stress
Low	140302499	Sweden	USG100-PLUS Internal Database Error -18000	USG100 Plus	The error message "Error Number: -18000 Error Message: Internal database error!" pops up on the GUI.
High	140401076	UK	USG 200 High CPU Usage	USG200	USG 200 High CPU Usage
Medium	140500238	NL	Adjust Helo packet	USG300	When sending the daily report email, the email is sent with the value "localhost" under the EHLO packet. The customer wants to know if it is possible to change this value to a FQDN or a IP. With the enhancement, If domain name is set then domain name is used; otherwise if system name is set then system name is used (Note: USG has a default system name); otherwise localhost is used.
			WK19-r52324 (2014/05/26)End		
Medium	140500954	CH	USG-200 Antispam issue mail header is cut off after 50 caracters	USG200	When enable Anti-Spam, the Email subject over 50 characters, the subject will been cut. SPR: 140220508

			WK21-r52379 (2014/06/09)End		
N/A	Internal	N/A	Duplicated BWM default rule priority CLI command in startup-config.conf.	N/A	Duplicated BWM default rule priority CLI command in startup-config.conf.
Low	140500193	US	USG: 3G Support	USG50	3G card USB760 doesn't work.
Medium	140600349	US	Issues with Content filter on USG 100	USG100	Content Filter doesn't work
Medium	140600427	US	USG300 high CPU with AV	USG300	USG300 high CPU with AV
			WK23-r52881 (2014/06/23)End		
N/A	Internal	N/A	Traffic statistics function can enter fastpath	N/A	Traffic statistics function can enter fastpath
Low	140600955	UK	USG 1000 license Transfer	USG100	Cannot sync with myzyxel.com 2.0.
Medium	140600333	CZ	USG 100 and connectivity check and fail back	USG100	If WAN interface was set to down via connectivity-check for around 15~30 minutes, after the WAN interface is up, the traffic will not pass through this interface unless I do some change in the WAN trunk. It only happens on the trunk interface with WRR load balancing algorithm.
Low	140500409	Sweden	ZyWALL 110 - Port logg Error (Feature Request)	USG Series	In the current design, Port 0 in the log is equal to P1 on the dashboard, and Port 1 in the log is equal to P2 on the dashboard, and so on.
			WK25-r53417 (2014/07/07)End		
N/A	Internal	N/A	When user set interface MTU, adjust mss automatically to resolve TCP fragmentation problem.	N/A	When user set interface MTU, adjust mss automatically to resolve TCP fragmentation problem.
N/A	Internal	N/A	Update OpenSSL to the latest version 1.0.0m	N/A	Update OpenSSL to the latest version 1.0.0m

Medium	140600040	RU	USG 2000 is rebooting when Anti-Spam on	USG2000	USG is rebooting when Antispam is on. It can reboot few times in hour. There is the message "sessions-limit" before each reboot. But it should not be the root cause. After turn off Antispam, USG works normally. SPR: 1407291192
Medium	140701233	RU	Problem with function of WAN port (DHCP client)	USG100	Problem with function of DHCP client on bridge interface. WAN2 (Zydmz_p2) + vlan6 are belong to br6 interface and DHCP server is connected to WAN2 physical port but br6 interface cannot get IP address. SPR: 1407311342
Low	140701524	UK	PCI compliance show vulnerable	USG50	PCI compliance show vulnerable.
Medium	140700657	Italy	external user/group and AD error	USG110	AD account can't be used to login or build SSL VPN with the message "Login Denied Validate user has failed."
			WK27-r53853 (2014/07/21)End		
N/A	Internal	N/A	Traffic cannot enter fastpath	N/A	Traffic cannot enter fastpath
Medium	140700610	CH	USG-110 exeptions don't work for Web Authentication using SSO	USG110	WAN interface setup as DHCP. The customer concern the default firewall rule blocking UDP 68 port traffic.(But WAN interface still get IP address success)
Medium	140800030	RU	Detect unexpected WLAN Problem	USG20W	Log message shows weird message
			WK29-r54225 (2014/08/04)End		
N/A	Internal	N/A	VRPT cannot receive about vlan and bridge syslog(4.10 model)	N/A	VRPT cannot receive about vlan and bridge syslog(4.10 model) SPR: 140822831

N/A	Internal	N/A	In Google chrome or Opera browser. Upload a file ,the screen always stay in the system that file to upload screen , even if the end of the upload.	N/A	In Google chrome or Opera browser. Upload a file ,the screen always stay in the system that file to upload screen , even if the end of the upload. SPR: 131213947
High	140701474	Sweden	Ghost calls v2	USG50	When SIP ALG is enabled, softphone located in lan will receive "ghost calls". Change AGL SIP default sip_direct_signalling and sip_direct_media was enable.
Medium	140800486	CH	USG-Series: DynDNS cannot add Pofile with starting number in Username	USG100	The DynDNS function can't use number as first characters.
Medium	140700610	CH	USG-110 exeptions don't work for Web Authentication using SSO	USG110	WAN interface setup as DHCP. The customer concern the default firewall rule blocking UDP 68 port traffic.(But WAN interface still get IP address success) SPR: 140814552
Low	140800119	UK	random dropping of sip calls	USG50	SIP phone call will be dropped randomly.
Medium	140800319	DE	USG210 / Download stock when UTM is activate	USG210	When enable UTM feature and start download it change from fast to slow step-by-step till "0" speed or just stuck and stop it.
Low	140800824	Sweden	USG(legacy)/ZyWALL series - IE10/11 issue	ZW1100	When using IE10/11 and go to Configuration > Firewall, you are able to activate/deactivate the "Enable firewall" button by clicking further to the right in the page. This issue doesn't exist when using Firefox nor Chrome. SPR: 140212279
Low	140800446	US	issues with secure-extender on USG 50	USG50	Cannot connect to CIFS server.
Low	140800582	CZ	ZyWALL 310 and 3 AD servers	ZW310	2nd and 3rd AD server will not be queried when logging via WEB GUI.

			WK33-r55083(2014/09/01)End		
			3.30 Patch 6 ITS Weekly FW start here (r55340)		
N/A	Internal	N/A	rename config file to 64 characters will fail with wrong CLI command	N/A	The limitation of filename length are different between GUI, CLI, and help document. SPR: 140922847
N/A	Internal	N/A	CLI to match internal and external interface name. Customers need to realize what the iface on the SNMP	N/A	Add a new CLI command to show the relationship between internal and external interface name. "debug interface show mapping"
N/A	Internal	N/A	CLI to match internal and external interface name. Customers need to realize what the iface on the SNMP	N/A	Add a new CLI command to show the relationship between internal and external interface name. "debug interface show mapping"
N/A	Internal	N/A	html_mailer daemon dead		html_mailer daemon dead
Medium	140600094	NL	Genexis model same problem	USG20/20w/50	Update driver to fix IOP issue with Genexis FiberXport device.Affected products include USG20/20w/50.
Medium	140900251	CH	USG-110 maximum characters for the configuration-filename	USG Series	In configuration file system. Renaming a config file and save it. (123456789012345678901234567890123456 7.conf)The characters can over 25. SPR: 140922847
Medium	140701132	CH	USG-100 read Ipsec and CPU information using snmp	USG Series	Add SNMP VPN status and connection counter MIBs.
Medium	141000164	IT	block problem on usg2000 (gold reseller EDP RENT)	USG2000	After upgrading the firmware to 3.30 (AQW.5), the customer has the same problem. Device will crash.
Critical	141000156	CH	DHCP Client wrong (Ticket based on SBG3300 but all USG also affected!)	USG Series	DHCP Client wrong (Ticket based on SBG3300 but all USG also affected!)

			WK39-r56048(2014/10/06) End		
Critical	141000155	CH	USG1100: IKE packet sent at wrong interface and wrong IP	USG1100	IKE packet sent at wrong interface and wrong IP
Medium	140900251	CH	USG-110 maximum characters for the configuration-filename	USG110	In configuration file system. Renaming a config file and save it. (123456789012345678901234567 89012345678901234567 .conf) The characters can over 25.
Medium	140900380	Germany	USG-1000 / L2TP can´t login user, crazy log message	USG1000	Unable to build L2TP connection from iPad2 and Android(4.4.4) phone. The connection is built successfully but closed right after.
Low	141000032	Taiwan	USG100-plus APP watch dog	USG100 Plus	The alert log "Image filesystem usage reaches 95%" appears in the log periodically.
			WK41-r56401(2014/10/20) End		
Low	141000460 141000462	CH	Static ARP entry will gone if enabling device HA	USG110	Static ARP entry will gone if enabling device HA
Low	141000458	CH	USG all: static ARP entries get lost after some time	USG110	After add static IP & MAC on device. After few days the record is gone.
Medium	141000978	Germany	USG-300 / limited admin cause GUI timeout when edit policy route under 3.30(AQE.6)ITS-WK39-r56048	USG300	Limited admin account is unable to view detailed configuration of policy rules.
Low	141000788	Netherlands	USG 100 SSLv3	USG Series	Turn off SSLv3 Support in Built-in serivce
Medium	140800642	Sweden	ZyWALL 1100 - VPN issue	ZW1100	Two VPN tunnels(site to site VPN) use the same phase 1 setting. Only one of the tunnels can be established. SPR: 140714684, 140804120, 141103007
Low	141001045	Taiwan	USG 100/60/20 WebGUI show License Status error	USG Series	It shows incorrect expiration date of licenses on the GUI.

			WK43-r57017(2014/11/04) End		
N/A	Internal	N/A	PKI support SHA 384 and 512	N/A	PKI support SHA 384 and 512
Medium	141000951	CH	USG310: New Problems with SHA-2 intermediate Certificate	USG Series	When using for SHA256 as intermediate certificate, the certificate path will shows "incomplete path".
Low	141100097	PL	VPN with certificate - USG200	USG200	Validation result of my certificate is failed.
Medium	141100282	Russia	USG50. Increased CPU usage on 3.30(BDS.6)	USG50	The customer updates the USG50 from 3.30(BDS.5) to 3.30(BDS.6) and can see that CPU Usage increased slightly. With no activity in the network the customer has 20-30% CPU usage instead 5% on 3.30(BDS.5).
High	141100177	Germany	ZyWALL 110 / VPN can´t build after rekeying reboot solve it	ZW110	VPN tunnels can´t be built up after rekeying without reboot.
			WK47-r57686 (2014/12/01)End		
N/A	Internal	N/A	Support Session Status Update.	N/A	Support Session Status Update.
Low	141200132	SE	After changing the subnet mask, the pool size is still limited.	ZW310	After changing the subnet mask, the pool size is still limited.
Low	141100648	CH	USg200: unencrypted password in config File	USG200	Password didn't encrypt in diaginfo.
Medium	141200336	US	dyndns update failing on .6 firmware	USG50	DDNS cannot be updated successfully.
Medium	141100032	DE	USG310 / request need "space" for certificate	USG310	Support space as following field: Organizational Unit, Organization, Town, State (Province), Country.

Medium	141100945	Russia	USG1000 - Device HA	USG1000	Failed to synchronize backup device with master device. When trying to sync backup device manually, backup device receives the signature from master, the synchronize status gets stuck in "Retrieving schedule-run sync for schedule-run has succeeded". Then backup device reboots, but booting from startup-config.
Medium	141100552	China	IDP signature cannot update in China.	USG1000	Unable to update IDP signature after upgrading from 3.30(AQV.2) to 3.30(AQV.6).
Low	141000415	Germany	ZW 1100 3.20 ITS WK 25 loses VPN Connection	ZW110	The tunnel shows to be up in VPN Connections in both sides. However, no traffic can pass the tunnel and the log on ZW1100 side shows tons of IPsec error with "no rule found, Dropping ESP packet"
High	140900236	Germany	USG-100 / VPN Nailed Up issue	USG100	Tunnels to the other USG 100 disconnect after some days working normally. The tunnel is not up and it cannot be connected until Inactivate and Active the tunnel.
Low	141100745	CH	USG-110 HA and ARP-table-entry of the management IP	USG110	Management IP will carry dynamic MAC.
Low	140800138	CH	All USG Serie: log error mailed	USG110	The log msg="/USR/SBIN/CRON: (root) MAIL (mailed 369 bytes of output but got status 0x0001)" is shown at debug log.
Low	141100761	CH	PAM-env: Unable to open config file: No such file or directory"	USG200	Device will keep printing specific log on Monitor page.

Medium	141100753	Russia	USG300 - Signature Released Date	USG Series	The latest release date of IDP signature is "2014-11-19 09:31:07". The customer found last week that this time has not yet come. The release date of IDP signature is "2014-11-19 09:31:07", but the current time at the customer's site is "2014-11-19 09:25:24"(GMT+3). We change to show correct release date based on device zone setting.
			WK51-r58270 (2014/12/21)End		
			3.30 Patch 7 ITS Weekly FW start here		
N/A	Internal	N/A	Do IxAutomate(UDP) throughput, USG300 crash	N/A	Do IxAutomate(UDP) throughput, USG300 crash SPR: 141222170
N/A	Internal	N/A	In VLAN and Bridge after changing the "IP Pool Start Address" and "Subnet Mask", the pool size is still limited.	N/A	In VLAN and Bridge after changing the "IP Pool Start Address" and "Subnet Mask", the pool size is still limited. SPR: 141229525
Medium	141100503	CH	ZyWALL 310 - Strange behavior when ZyWALL is in DNS proxy role	ZW310	When query old domain in few seconds, the USG will re-queried with internet again
			WK03-r58599 (2015/01/26)End		
N/A	Internal	N/A	Add new CLI command and enhance load-balance debug message	N/A	Add two new CLI command show routing cache "debug system ip route show cache" enable/disable/show load-balance debugging: "debug system load-balance {enable|disable|show}"
Medium	141100624	CH	USG-20 CPU load higher after update to patch 6 wk43	USG20	The bug fix is for another issue which IPSec daemon will cause CPU high.
Medium	141201088	Russia	USG100+ - Email Daily Report	USG100	In MONITOR > Anti-X Statistics > Anti-Virus, the number of total files scanned is 0.

High	150200023	TH	USG 300 /TH/ Thaimart: USG300_reboot issue.	USG300	Customer have USG300 and they noticed device will reboot once the CPU usage is too high.
Medium	150200052	CH	USG40W: DDNS dynu can't work	USG40W	The DDNS can't update success
Medium	141100801	Russia	USG 300 problems on 3.30(AQE.6) and 3.30(AQE.6)ITS-WK43	USG300	Device zysh daemon crashed.
Medium	150200142	CH	USG110 WPA2-enterprise for controlled ap not working when using ad as aaa-server	USG110	Fix some potential bug.
			WK06-r59262 (2015/02/16)End		
Medium	150300152	CH	USG100 zysh daemon crash after adding fifth dns server on wan1 port	USG100	Device with the problem when added 5th DNS server on WAN1 interface.
Low	150100588	IT	ip http secure port issue on applying startup-config.conf	USG110	Fix to use GUI to upload the startup_config.conf may cause to alert error message.
Medium	150100917	Russia	New OID for USG series	USG Series	The customer asks to add the following OIDs: -VPN uptime and timeout (lifetime) - the number of packets and octets through the VPN-connection
			WK09-r59684 (2015/03/16)End		
N/A	Internal	N/A	Certification issue in VPN GUI.	N/A	Set a vpn rule to use certifiaction, then modify certification's name. In vpn phase1 certification setting become null and reboot DUT will let device change to default setting SPR: 150306441

N/A	Internal	N/A	Modify OIDs value from string to counter64	N/A	Modify the following OIDs from string to counter64: 1.3.6.1.4.1.890.1.6.22.2.6.1.6 --> Number of in-bound packets for the connecition 1.3.6.1.4.1.890.1.6.22.2.6.1.7 --> Number of in-bound octets for the connection 1.3.6.1.4.1.890.1.6.22.2.6.1.8 --> Number of out-bound packets for the connection 1.3.6.1.4.1.890.1.6.22.2.6.1.9 --> Number of out-bound octets for the connection
N/A	Internal	N/A	Device will apply lastgood.conf when reboot if enable policy enforcement in VPN connection rule which is added in VPN concentrator	N/A	Device will apply lastgood.conf when reboot if enable policy enforcement in VPN connection rule which is added in VPN concentrator SPR: 150422472
N/A	Internal	N/A	Fix a vulnerability issue	N/A	The vulnerability we found on your equipements is that the web interface does not filter parameters. If an external user initiates a tcp connection on the equipment he can request internal websites.
N/A	Internal	N/A	Import duplicate certificate into device may cause IPSec tunnel cannot build up.	N/A	Import duplicate certificate into device may cause IPSec tunnel cannot build up. SPR: 150306457
Medium	150300789	Russia	USG20W – WLAN GUI	USG 20W	In the settings of WLAN-interface, the input fields "802.11 band" and "Channel" are incorrectly positioned. The problem occurs only in the browser IE 11.
Medium	150200484	CZ	USG1000 / CZ / crash with new firmware	USG1000	Not possible to log in to WEB GUI and SSH after upgrading to 3.30(AQU.7)

Critical	150200430	FR	Operat2000 - Packet SIP	USG200	Customer has set WAN1 and WAN2_PPP as trunk. When WAN1 interface is dead, then traffic will pass through to WAN2_PPP interface. But after WAN1 interface is back(Or WAN2_PPP is dead), the SIP traffic pass through to WAN1, but will using for WAN2_PPP IP address.
Low	150301062	CH	USG310: VLAN interface strange behavior	USG310	Different behavior for VLAN interface before/after rebooting.
Low	150300850	NL	USG60 IP/MAC binding - Static DHCP table	USG60	The customer recently tried to add the 97th static DHCP address and received an error that the limit(96) had been reached, but the USG still partly updated the startup-config file that then created an "incomplete entry" error each time the USG rebooted. He has to edit the startup-config and removed the partial static entry and all was well again.
Medium	150400334	Russia	USG 300. zysh daemon crash	USG300	This is the same ticket as #141100801 USG 300 problems on 3.30(AQE.6) and 3.30(AQE.6)ITS-WK43. The customer replied the device crashed again. It was without any load. No traffic, only console connected.
			WK18-r61075 (2015/05/04) End		
N/A	Internal	N/A	Fix CSRF Pharming vulnerability	USG series	Fix CSRF Pharming vulnerability
N/A	Internal	N/A	Modify interface wan1 IP(With ITS ticket#150600524 configuration), device produce coredump	N/A	Modify interface wan1 ip(With ITS ticket#150600524 configuration), device produce coredump SPR: 150622302
Medium	150301046	CH	FTP Access to Device thru IPSec VPN Tunnel	USG20W	It's not possible to access on USG through an IPSec VPN Connection (C2S or S2S) by ftp if TLS is mandatory.

Critical	150200430	FR	Operat2000 - Packet SIP	USG200	Customer has set WAN1 and WAN2_PPP as trunk. When WAN1 interface is dead, then traffic will pass through to WAN2_PPP interface. But after WAN1 interface is back(Or WAN2_PPP is dead), the SIP traffic pass through to WAN1, but will using for WAN2_PPP IP address.
Medium	150400882	Russia	ZyWALL310 - Incorrect sorting by columns	ZW310	When trying to sort the table (Hits) in Dashboard by descending/ascending, sorting is only by the first digit.
Medium	150200663	DE	USG2000 / DE / Anti-Spam cause mail can't be arrived	USG Series	Mail from Internet > LAN with attached file (over 1~2MB) can't be arrived.
Critical	150500821	CH	USG110: LogJam vulnerability	USG Series	Current USG Serie is vulneral against the LogJam attack.
Medium	150100917	Russia	SNMP MIBs ifOperStatus and ifSpeed are incorrect for port-grouping interface	USG Series	SNMP MIBs ifOperStatus and ifSpeed are incorrect for port-grouping interface
High	150600688	DE	USG-300 / crash with WK09, WK18 for L2TP with kernel issue	USG300	USG300 will crash if trying to establish L2TP.
Medium	150600082	US	CF Report Server Not Showing or Reporting Any Statistics	USG210	The CF report in monitoring page and report server record not match.
Medium	150600368	CH	USG110 - Can't send log with SSL encryption with some providers	USG110	Some ISP mailserver does not support STARTTLS. We add a option to diable STARTTLS and use SMTPS.

High	150500671	USA	ooss - Charter Comm, home USG having non-specific failure to pass traffic	USG20	The device work fine for few days, but when symptom happening the device can't access to internet any more.(needs reboot device to recover it)
Medium	150600437	FR	Issue HA USG300	ZW310	After inactivated VLAN10 interface. And pickup device HA function(then device will transmitted GARP to internet), and PC will got IP address from inactive VALN interface.
Low	150500319	SE	After rebooting USG, the customer has to remove and add the cellular interface from WAN zone.	USG40W	After rebooting USG, the customer has to remove and add the cellular interface from WAN zone.
Medium	150700285	CH	Local PC use FTP Client cannot list Remote DUT by VPN tunnel.	USG20W	Topology: PC1---DUT1---WAN---DUT2----PC2 1. DUT1 built IPSec VPN tunnel with DUT2 2. PC1 use FTP Client access DUT2 3. FTP login is OK. But it cannot do list action
Low	150700094	DE	Create DSA Cert SelfSigned not shown in GUI but FTP Folder of USG.	USG20	DSA 1024 bits certificate can be generated. It can be searched via FTP, but not via GUI.
Medium	150700521	CZ	ZyWALL110 / CZ / ZyWALL110 PPPoE issue	ZW110	Strange PPP behavior while there's specific combination of characters in username ($ and @)
Low	150600680	HK	[USG50]500M drop throughput to 100M	USG50	The customer has 500M link from ISP. When ISP is connected directly to PC, download/upload speed is around 500Mbps which is tested on www.speedtest.net. When ISP is connected to USG with default configuration, download/upload speed is around 280Mbps which is a normal throughput. However, after he configures virtual interface and some VLAN, the throughput becomes 100Mbps.

Medium	150200529	NO	ZyWALL110; DUID input fields is too small	ZW110	DHCPv6 DIUD is too small.
Medium	150600067	CH	USG100 DHCP server size > 254	USG Series	By default configuration: LAN1 192.168.1.1/24 LAN2 192.168.2.1/24 DMZ 192.168.3.1/24 Changed LAN1 interface as 192.168.1.1/16 and extended DHCP pool size more than 255, the PC can't get IP address success. The interface LAN1 IP address is overlap with other interface subnet. We enhance this by add a check on GUI to show warning message on overlap issue.
Medium	150600248	CH	USG100: DHCP Deamon dead	USG Series	The DHCP daemon not response to client. DHCP daemon dead is caused by device configuration conflict that virtual server original IP address is not belong to the subnet of incoming interface. We enhance it by add a check for the non-matching issue.
Medium	150701098	CH	USG110 radius daemon restarts every 3 minutes	USG110	USG110 radius daemon restarts every 3 minutes The symptom can be reproduced after applied customer's configuration. The space character in group-id generates wrong groups_radius configuration file and causes radiusd to exit with error during startup.

			WK30-r62867 (2015/08/06) End		
N/A	Internal	N/A	eITS#150300296 and 150900099, we enlarge the maximum number the time period of connectivity check.	N/A	Was: The maximum number the time period of connectivity check is 600 seconds Is: The maximum number the time period of connectivity check is 3600 seconds
Medium	150701098	CH	USG110 radius daemon restarts every 3 minutes	USG110	The RADIUS daemon dead per 3 minutes.
Low	150700599	CH	UNC Path too short	USG60	The table of file sharing path, the folder length can't over 12 character.
Medium	150600067	CH	USG100 DHCP server size > 254	USG Series	By default configuration: LAN1 192.168.1.1/24 LAN2 192.168.2.1/24 DMZ 192.168.3.1/24 Changed LAN1 interface as 192.168.1.1/16 and extended DHCP pool size more than 255, the PC can't get IP address success. The interface LAN1 IP address is overlap with other interface subnet. We enhance this by add a check on GUI to show warning message on overlap issue.
Medium	150600248	CH	USG100: DHCP Deamon dead	USG Series	The DHCP daemon not response to client. DHCP daemon dead is caused by device configuration conflict that virtual server original IP address is not belong to the subnet of incoming interface. We enhance it by add a check for the non-matching issue.
Low	150600243	DE	USG60W Configuration issue	USG60W	It will take a long time to show the application object.
Medium	150700453	Russia	ZyWALL 310. Incorrect sorting by columns	ZW310	Incorrect sorting in MONITOR>UTM Statistics>IDP>Occurrence. Network>NAT>Priority

Medium	150700745	Russia	USG50 - Email Daily Report through IPSec	USG50	The customer is configured the Email Daily Report to send reports on a mail server that is located behind the IPSec-tunnel. Ping from the device to the mail server 192.168.5.15 successfully, but reports are not sent
Medium	150801051	DE	USG200 / Tip 5 virus in dashboard go to wrong link	USG200	Top 5 virus cannot be queried.
Medium	150800760		VRPT error message with USG100-PLUS	USG100 plus	VRPT will show error message with USG100-PLUS.
High	150900159	TR	TR/ USG100 plus/ unable to login to device	USG100 plus	Customer have report that they can't login to device, encounter the same result after reboot.
			<mark>WK37-r64152 (2015/09/21) End</mark>		
N/A	Internal	N/A	Enhance DHCP server to support PXE scenario.	N/A	Enhance DHCP server to support PXE scenario.
N/A	Internal	N/A	Modify DHCP Server Extended Options of EthernetEdit GUI page, the dhcpd.conf don't update immediately.	N/A	Modify DHCP Server Extended Options of EthernetEdit GUI page, the dhcpd.conf don't update immediately.
Medium	151000311	Russia	USG20. Highest Bandwidth Priority for SIP Traffic	USG20	There is no option "Enable Highest Bandwidth Priority for SIP Traffic" on USG20's web-gui as on other ZyWALLs but there is the command in CLI "bwm highest
Medium	150901015	RU	After rebooting the USG20 does not rise PPPoE automatically	USG20	After rebooting the USG20 does not rise PPPoE automatically.From the packet trace of customer's USG20 WAN, there's no PADI from USG20.The customer claimed that PPPoE could be connected if dial manually, but not automatically.

Medium	151001056	Russia	USG 100 - Time Zone	USG100	Moscow, Kazan, Volgograd is using GMT+3 (without daylight savings), but in settings of USG it is GMT+4.
			WK45-r65027 (2015/11/09) End		
N/A	Internal	N/A	Add CLI to skip that connection removed immediately while 1.ICMP unreachable 2.ICMP TTL Expired	N/A	CLI command example: #firewall icsa icmp-destroy-session enable #show firewall icsa status
Medium	151100441	DE	USG210 / Daily report issue if use password with " , "	USG210	USG will not detect the incorrect character.
Low	150800878	CH	Error IP format still saved into configuration by CLI command	USG110	IP format in CLI command has changed. It does not allow to enter "00" or "0" before the decimal number.
Medium	151101099	Russia	USG50 - Console_Web	USG50	Unable to access the console from web if using Java 8 update 51 or above (any browser). There is no problem with Java 8 update 45 and below
Medium	151200409	USA	logo not working after log in	USG20	The logo not work in session page.
			WK49-r66311 (2015/12/14) End		
N/A	Internal	N/A	Improving IDP signature update to avoid system crash.	N/A	Improving IDP signature update to avoid system crash.
			WK52-r66827 (2015/12/14) End		
N/A	Internal	N/A	DNS Inspection support for all Legacy model.	N/A	DNS Inspection support for all Legacy model.
N/A	Internal	N/A	Support Huawei E3533	N/A	Support Huawei E3533
N/A	Internal	N/A	DNS Inspection for CF or IDP license	N/A	Include a bug fix for GUI for black list enter "*twitter*"
Medium	160100248	Taiwan	Policy route cannot control IPsec rule	USG100	The customer build site to site VPN between two sites. There is no problem to ping each other when VPN tunnel is established.
Medium	160100922	CH	USG20W: VPN Site to Site disconnects all the time (Brandi)	USG20W	In the log shows the tunnel will disconnect immediately after tunnel established success.

Medium	150701098	CH	USG110 radius daemon restarts every 3 minutes	USG110	The RADIUS daemon dead per 3 minutes.
Low	160100264	DE	L2TP auth. to Radius does not works after update from 413p1c0 to 413p1_wk49.	ZW1100	After upgrading to wk49, L2TP cannot be authenticated via radius server.
Medium	150401063	CH	SHA2 support	USG110	1. USG can self generate certificates with the SHA-2 hash 2. During Microsoft and Google will not support for SHA2 certificate in 2016, so most enhancing it before 2016. 3. CA generator replaced by OpenSSL.
			WK08-r68696 (2016/02/27) End		
N/A	Internal	N/A	When IPsec tunnel with domain name in my address/peer address, the tunnel cannot live too long.	N/A	When IPsec tunnel with domain name in my address/peer address, the tunnel cannot live too long.
N/A	Internal	N/A	CVE-2015-7547 vulnerability	N/A	CVE-2015-7547 vulnerability
			WK10-r68992 (2016/03/09) End		
N/A	Internal	N/A	When IPsec tunnel with domain name in my address/peer address, the tunnel cannot live too long	N/A	The internal rule point of ext_config was not updated to the new address when DNS query updates an internal rule. If someone removes the rule configuration from Quicksec, the remove mechanism will remove wrong internal rule.
Low	160200257	DE	The VPN tunnel can't establish success.	USG2000/USG20	Remove the "DONT FRAGMENT BIT" from IP header of IKE packet for the MTU issue.
Medium	160400995	Russia	RDP service through SSL tunnel can't use FullScreen mode (on IE11).	USG40W	The root cause is geting local disktop size absolute value, the solution is setting Full tunnel automatic.
			WK19-r70729 (2016/05/10) End		
N/A	Internal	N/A	Add ISAKMP VID for ZyXEL USG/ZyWALL and ZyXEL ZLD.	N/A	To distinguish the ISAKAMP is from ZyXEL or other vendor.

			WK22-r71231 (2016/06/02) End		
N/A	160600575	Russia	Customer set a set a ppp interface and name "eth1" and then users apply the configuration file(startup-config). It will show the error message "% System fatal error: 3005105." on the console.	USG50	GUI don't limit the reserved words name(ex: et, vlan, br). It affect mapping external interface name into internal interface name wrong when xml get the correct rip interface information.
			WK28-r72114 (2016/07/14) End		
Medium	160800459	Russia	USG 50. AD		The customer has problem with authorization external user on AD through ZyWALL. The user mizurev belongs to the group Programmers. The user mizurev can pass validation on AD but the test result of the ext-group-user shows the user mizurev doesn't belong to this group.
N/A	Internal	N/A	Upgrade to openssl-1.0.2a for TLS1.2 support	N/A	Upgrade to openssl-1.0.2a for TLS1.2 support
N/A	Internal	N/A	Ipad mode config+L2TP sress produce core dump	N/A	In devcie 40w setting mode config and L2TP - that ipad mode config and pc L2TP conection success - that ipad and pc conection internet: youtobe, line, yahoo......etc - device produce coredump after 1 hr
N/A	Internal	N/A	Setting mode config and L2TP, PC can not connection L2TP tunnel	N/A	In device setting: ipad mode config and L2TP - connection L2TP success first, then connection ipad mode config success - connection ipad mode success first, then connection L2TP fail

N/A	Internal	N/A	Add CLI command to disable abnormal tcp flags detect.	N/A	Disable detect : "firewall abnormal_tcp_flag_detect deactivate" Enable detect : "firewall abnormal_tcp_flag_detect activate"
			WK41-r74145 (2016/10/14) End		

Know Issue:

FW Vesion	Model	Symptom	Reported date	SPR No.
ITS-r34073	USG1000	Symptom: If we import multiple certificate with **same subject name** to my certificate, then the IPSec VPN tunnel with certificate will fail to build up	2012/07/25	120725857 120718294 120725860
ITS-WK45-r36005	USG2000	User can't use IE browser login to device with GUI when device use certificate with RSA keys less than 1024 bits in length for HTTPS service. Note: The user will encounter this issue only if user had update Microsoft security patch (2661254: Update for minimum certificate key length. http://technet.microsoft.com/security/advisory/2661254). **Workaround: Customers need to use certificates with RSA keys greater than or equal to 1024 bits in length for HTTPS service.**	2012/11/23	121123900
ITS-WK47-36239	All	The below four cases, the EPS checking details will pass when EPS checking condition select (B) but client install (A) software. 1.(A)McAfee AntiVirus Plus 2012, (B)McAfee AntiVirus Plus 2011 2.(A)McAfee Internet Security 2012, (B)McAfee Internet Security 2011 3.(A)McAfee Total Protection 2012, (B)McAfee Total Protection 2011 4.(A)Avira AntiVirus 2012, (B)Avira AntiVirus Personal 2009	2012/11/26	N/A