

## Support company products partners support contact

Release Notes for 3.1.7(GWg) -- Sipura Phone Adapter SPA-3000

SPA-3000 -- 1 Port FXS, 1 Port FXO, 1 Ethernet Interface

Copyright (C) 2003-2005 by Linksys, A Division of Cisco Systems, Inc.

\* Use of Proprietary Information and Copyright Notice:

 $^{\star}$  This release note document contains proprietary information  $^{\star}$ 

\* that is to be used only by Sipura Technology customers.

\* Any unauthorized disclosure, copying, distribution, or use

\* of this information is prohibited. This restriction includes \*

\* ALL Internet based discussion forums, e.g. DSLreports. \*

==========

## BUG Fixes

==========

-- since 3.1.7 --

- . Fixed URL/IP address configured in speed dial problem
- . If inbound INVITE does not have contact header, SPA will send 400, but followed by 100, and 180 which is not correct