



Firmware Release Note

P-660HW-D1

Switzerland version

Release 3.40(APC.4)D0

ZyXEL P-660HW-D1 Switzerland Version Release 3.40(APC.4)D0 Release Note

Date: May 6, 2009

Supported Platforms:

ZyXEL P-660HW-D1

Versions:

ZyNOS Version: V3.40(APC.4) | 05/06/2009 13:17:00

Bootbase Version: V1.06 | 1/20/2006 9:44:11

Notes:

The P-660HW-D1, is 4th generation of ZyXEL ADSL product family. It is a high performance ADSL/ADSL2/ADSL2+ router for small/medium office to have Internet access and LAN-to-LAN application over the existing copper line. P-660HW-D1 takes advantage of much higher data rate than ADSL, speed up to 12Mbps (ADSL2) or 26Mbps (ADSL2+), greater reach, faster start-up, advanced diagnostics and better power management. This high performance ADSL router is a high integrated advanced Firewall, Bandwidth Management and IEEE 802.11g wireless features to meet the demand of high-end market.

P-660HW-D1 provides an embedded mini-PCI module for 802.11g Wireless LAN connectivity, four single auto-sensing, auto-detection 10/100BASE-T Ethernet ports for connection to the user's local network, and a single RJ-11/RJ-45 port for connection to ADSL/ADSL2/ADSL2+ line.

ADSL data pump version: TI AR7 07.00.04.00

Features:

Modifications in V 3.40(APC.4)D0 | 05/06/2009

1. Change to FCS

Modifications in V 3.40(APC.4)b1 | 04/17/2009

1. Change default romfile and fix the Mandatory bugs

- 1) change default romfile
- 2) [Customize Feature]
Web-redirect page should be <http://192.168.1.1/rpAuth.html>, Force customer to change the router Password on the first step configuration
- 3) [Customize Feature]
WLAN-Wizard: If a user uses the wizard to disable wireless LAN, the WLAN will come up again after a few seconds as long as the time of the schedule is set to 00:00 - 23:59 (default), Customer decision if he need to disabled WLAN manually. The wizard should set the time to 00:00 - 00:00 or 00:00-23:59, depending on the Marking of the "Active []" choice in the wizard.

- 4) [BUG FIX] SPRID:090417161
Symptom: Only for GERMAN language - WLAN:“Netzwerkverkehr zwischen WLAN und WAN blockieren”, Should be “Netzwerkverkehr zwischen WLAN und LAN blockieren” modify WAN with LAN.
- 5) [Customize Feature]
If customer disable WLAN on Wizard the Wizard should NOT display the next html page with WLAN setting
- 6) [BUG FIX] SPRID:090417162
Symptom: ADSL device starts PPPoE session at 12:00
Condition: Originally device will check the syslog Server IP Address in Maintenance>Logs>Log settings if it is not empty address (0.0.0.0 is not empty for device), device will trigger PPOE dial up.